

PA-18 Fuel Valve Line Fit

Once in a while a customer will complain that he cannot install one of the fuel lines because it is too close to the valve. This is because the 3400X4 fitting is threaded a thread or two too deep. The fix for this situation is to provide the customer a Weatherhead 3200X4 fitting. This is to be installed between the 3400X4 and 600X6 fittings.

Installation Note for U491-947K (PA-18)
To determine if the Weatherhead
3400X4 Elbow is threaded too deep.

