

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 47-20-02

Airworthiness Directives; Aeronca Model 7AC Airplanes

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

47-20-02 AERONCA: (Was Mandatory Note 2 of AD-761-2 and Mandatory Note 2 of AD-759-3.) Applies to 7AC Airplanes Having Serial Numbers 226 to 3721; and 11AC, Serial Numbers 1 to 351.

Compliance required at next periodic inspection but not later than August 1, 1947.

To prevent the oleo strut assembly from separating in flight, replace the fiber piston with aluminum pistons. (Supplementary to Aeronca Service Helps and Hints No. 12 dated February 11, 1947, covers this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)