

Airworthiness Directive

▼ Federal Register Information

This information is not available.

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

AD 50-07-01

Airworthiness Directives; ERCO Model 415C, 415CD and 415D Airplanes
PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

▼ Regulatory Information

50-07-01 ERCO: Applies to Ercoupe Models 415C (Which Incorporate Adjustable Elevator Trim Tabs), 415CD, and 415D Airplanes.

To be accomplished by September 1, 1950.

To preclude the possibility of elevator flutter in the event the elevator trim tab control wire fails, elevator trim tab stop and spring, Erco P/N 415-SK-287 and 415-22035 should be installed.

(Engineering and Research Corp. "Ercoupe Service Memorandum No. 55 and 55A" cover this same subject.)

▼ **Footer Information**

▼ **Comments**

FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help

Readers & Viewers: [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)