

## Airworthiness Directive

### ▶ Federal Register Information

#### ▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

### AD 51-23-03

Airworthiness Directives; Piper Models PA-16, PA-20, and PA-22 Aircraft

**PDF Copy (If Available):**

#### ▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

#### ▼ Regulatory Information

**51-23-03 PIPER:** Applies to Model PA-16 Aircraft, Serial Numbers 16-1 and Up; PA-20 Aircraft, Serial Numbers 20-1 Through 20-802; and PA-22 Aircraft, Serial Numbers 22-1 Through 22-348.

Compliance required as soon as possible, but not later than October 15, 1951.

Install insulators of sufficient area inside the battery box cover over the battery terminals to positively prevent a metallic contact between the wing nuts or terminals and cover. Hard fiber rubber or phenolic insulating materials 1/16-inch minimum thickness may be used.

(Piper Service Bulletin No. 118 covers this same subject.)

▼ **Footer Information**

▼ **Comments**

**FAA.gov Home | Privacy Policy | Web Policies & Notices | Contact Us | Help**

**Readers & Viewers:** [PDF Reader](#) | [MS Word Viewer](#) | [MS PowerPoint Viewer](#) | [MS Excel Viewer](#) | [WinZip](#)