

Model: A2

Serials: A-2 thru A-8

Subject: Wire Change in Generator to Regulator Wiring

A correction in the wiring on current models coming off the line has been incorporated to completely eliminate the remote possibility of overheating the generator if for some reason the master switch is turned off in flight for a prolonged period of time. The change consists of merely reversing the two wire connections on the generator and two of the wires on the voltage regulator. The final configuration should be as shown below.

**NOTE:** The final dash number of the wire part number will be found on the wires in the airplane to aid in tracing connections.

