

IMMEDIATE ACTION

**SERVICE**

NUMBER 85




**BULLETIN**

April 25, 1946

SUBJECT: REWORKING OF BOTTOM COWL FOR REPLACING AIR SCOOP  
EQ5259 WITH EQ5370 (CONTINENTAL PART NUMBERS)

MODELS AFFECTED: J3C AIRPLANES

When replacing the vertical faced filter air scoop (Part No. EQ5259) with the new slant faced filter air scoop (Part No. EQ5370), the bottom cowl assembly will have to be reworked as per sketch below.



ENGINE BOTTOM COWL FRONT

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.