



Customer Services

SERVICE LETTER

No 259

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

November 30, 1955

TO: All Distributors, Dealers and Owners

SUBJECT: RPM Restriction Placard

MODELS AFFECTED: All PA-18 "150", PA-18A "150", PA-22 "150" Airplanes

We have been advised by the Engineering Department that the placard which states:

AVOID CONTINUOUS OPERATION ON THE GROUND
BETWEEN 2050 AND 2250 RPM

can be removed immediately from the above mentioned airplanes.

This placard is no longer necessary.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Rolland Boardman
Service Manager

RB:gh