

# **Technical Support**

## **Subject**

2014+ Ram 5.7L and 6.4L HEMI Dual Alternator to Single Alternator

### **System or Parts affected**

UNDERHOOD™ 70 (V900118)		UNDERHOOD™ 70 (V900119)		
5.7L Hemi Gas	2014-2018		5.7L Hemi Gas	2014-2018
6.4L Hemi Gas	2500 – 3500 Pick Up		6.4L Hemi Gas	3500 – 5500 Chassis Cab

UNDERHOOD™ 70 (V900128)						
6.4L Hemi Gas	2019+ 2500-3500 Pick Up					
	2019+ 3500-5500 Chassis Cab					

#### Overview

#### **Background:**

The UNDERHOOD™ systems listed above are not compatible with the specified dual alternator equipped vehicles unless the vehicle is converted to a single alternator system.

#### Resolution:

- The vehicle needs to be taken to a Ram dealer prior to removing the secondary alternator. Ram technicians will utilize the WiTech service tool to re-program the truck's factory firmware to disable the second alternator. This eliminates the need to jumper or splice any wires.
- · Remove secondary alternator and belt.



Note: Please see Ram Body Builder Notice prior to comencing any conversion on the 6.4L Gas Engine.

https://www.ramtrucks.com/assets/bbg/pdf/2016/docs/ram/ramdad.pdf



Document	Version	Department	Revision Details	Revised by	Tech	Engineering	Implemented
EXT-UH-004	Α	Tech	Model Year update	BDJ	N/A	CM	19 Nov 2020

Knowledge Base: http://kb.vmacair.com/ Email: tech@vmacair.com/ Web: www.vmacair.com/ Technical Support: 1(888)241-2289 Toll Free:1(800)738-8622 Fax: 1(877)740-3201